

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2063 Crows Landing

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|-------|------------|--------------------------|--------------------|
| Unit No. 01 San Joaquin River | Right | 10.44 | 05/12/2015 05/12/2015 | Richard Willoughby |

| | | | | | | | |
|--|----------------------------------|--------------|----|------------------------|----|-----|---|
| LM Start | 0.00 | Rating ** | A | Issue No. | 12 | | |
| LM End | 0.00 | Issue Type + | Ma | Location * | WS | | |
| Category | Earthen Levee | | | GPS Latitude/Longitude | | | |
| | | | | Start | | End | |
| Item | Operations & Maintenance Manuals | | | | ° | | ° |
| | | | | | ° | | ° |
| DWR ID | DWR_RD2063_01_s _ 2013_12 | | | | | | |
| Action/Comments | | | | | | | |
| Inspector Comments: The LMA maintains a copy of the O&M manual on file at district office. | | | | | | | |
| | | | | | | | |

No Photos

| | | | | | | | |
|--|--------------------------------|--------------|----|------------------------|----|-----|---|
| LM Start | 0.00 | Rating ** | A | Issue No. | 15 | | |
| LM End | 0.00 | Issue Type + | Ma | Location * | WS | | |
| Category | Earthen Levee | | | GPS Latitude/Longitude | | | |
| | | | | Start | | End | |
| Item | Emergency Supplies & Equipment | | | | ° | | ° |
| | | | | | ° | | ° |
| DWR ID | DWR_RD2063_01_f_2014_15 | | | | | | |
| Action/Comments | | | | | | | |
| Inspector Comments: The LMA maintains adequate flood fight supplies and equipment. | | | | | | | |

No Photos

| | | | | | | | |
|---|-------------------------------|--------------|----|------------------------|----|-----|---|
| LM Start | 0.00 | Rating ** | A | Issue No. | 21 | | |
| LM End | 0.00 | Issue Type + | Ma | Location * | WS | | |
| Category | Earthen Levee | | | GPS Latitude/Longitude | | | |
| | | | | Start | | End | |
| Item | Flood Preparedness & Training | | | | ° | | ° |
| | | | | | ° | | ° |
| DWR ID | DWR_RD2063_01_s _ 2013_21 | | | | | | |
| Action/Comments | | | | | | | |
| Inspector Comments: The LMA is prepared for flood response. | | | | | | | |

No Photos

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2063 Crows Landing

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|-------|------------|--------------------------|--------------------|
| Unit No. 01 San Joaquin River | Right | 10.44 | 05/12/2015 05/12/2015 | Richard Willoughby |

| | | | | | |
|--|---------------------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.01 | Rating ** | M | Issue No. | 27 |
| LM End | 10.40 | Issue Type + | Ma | Location * | CR |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Crown Surface / Depressions / Rutting | | | 37.478842 ° | 37.390455 ° |
| | | | | -121.044627 ° | -120.941945 ° |
| DWR ID | DWR_RD2063_01_s _ 2012_27 | | | | |
| Action/Comments | | | | | |
| Add appropriate material and re-grade the levee to bring the crown above the design elevation. | | | | | |

No Photos

| | | | | | |
|---|--------------------------|--------------|-----|------------------------|---------------|
| LM Start | 0.01 | Rating ** | A/W | Issue No. | 3 |
| LM End | 0.50 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 37.478550 ° | 37.471548 ° |
| | | | | -121.044603 ° | -121.044553 ° |
| DWR ID | DWR_RD2063_01_s _ 2012_3 | | | | |
| Action/Comments | | | | | |
| Remove the wild growth other than native grasses from the levee slopes. | | | | | |

Photo 1 of 1 : SP_2015_RD2063_112_3_20150309_00001.jpg



Looking south at typical view of waterside and landside slopes.

| | | | | | |
|---|--------------------------|--------------|-----|------------------------|---------------|
| LM Start | 0.01 | Rating ** | A/W | Issue No. | 2 |
| LM End | 0.50 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 37.478548 ° | 37.471545 ° |
| | | | | -121.044605 ° | -121.044553 ° |
| DWR ID | DWR_RD2063_01_s _ 2012_2 | | | | |
| Action/Comments | | | | | |
| Remove the wild growth other than native grasses from the levee slopes. | | | | | |

No Photos

| | | | | | |
|--|--|---|--|---|--|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement | |
|--|--|---|--|---|--|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2063 Crows Landing

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|-------|------------|--------------------------|--------------------|
| Unit No. 01 San Joaquin River | Right | 10.44 | 05/12/2015 05/12/2015 | Richard Willoughby |

| | | | | | |
|--|---------------------------|--------------|-----|------------------------|---------------|
| LM Start | 1.38 | Rating ** | A/W | Issue No. | 36 |
| LM End | 1.38 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 37.463582 ° | 37.463582 ° |
| | | | | -121.032263 ° | -121.032263 ° |
| DWR ID | DWR_RD2063_01_s _ 2013_36 | | | | |
| Action/Comments | | | | | |
| No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |

No Photos

| | | | | | |
|--|--------------------------|--------------|-----|------------------------|---------------|
| LM Start | 1.54 | Rating ** | A/W | Issue No. | 4 |
| LM End | 1.54 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 37.461322 ° | 37.461322 ° |
| | | | | -121.031785 ° | -121.031785 ° |
| DWR ID | DWR_RD2063_01_s _ 2012_4 | | | | |
| Action/Comments | | | | | |
| Exterminate rodents and backfill and compact or grout burrows. | | | | | |

No Photos

| | | | | | |
|--|---------------------------|--------------|-----|------------------------|---------------|
| LM Start | 1.65 | Rating ** | A/W | Issue No. | 11 |
| LM End | 1.65 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 37.459813 ° | 37.459813 ° |
| | | | | -121.032372 ° | -121.032372 ° |
| DWR ID | DWR_RD2063_01_s _ 2012_11 | | | | |
| Action/Comments | | | | | |
| No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |

Photo 1 of 1 : SP_2015_RD2063_112_11_20150309_00004.jpg



Looking east at squirrel holes on landside slope.

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2063 Crows Landing

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|-------|------------|--------------------------|--------------------|
| Unit No. 01 San Joaquin River | Right | 10.44 | 05/12/2015 05/12/2015 | Richard Willoughby |

| | | | | | |
|--|----------------------------|--------------|-----|------------------------|---------------|
| LM Start | 2.67 | Rating ** | A/W | Issue No. | 982 |
| LM End | 2.74 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 37.447512 ° | 37.446574 ° |
| | | | | -121.026050 ° | -121.025643 ° |
| DWR ID | DWR_RD2063_01_s _ 2012_982 | | | | |
| Action/Comments | | | | | |
| Repair the levee slope damaged by livestock and prevent large animal access. | | | | | |

No Photos

| | | | | | |
|--|---------------------------|--------------|-----|------------------------|---------------|
| LM Start | 3.14 | Rating ** | A/W | Issue No. | 37 |
| LM End | 3.14 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 37.442400 ° | 37.442400 ° |
| | | | | -121.023095 ° | -121.023095 ° |
| DWR ID | DWR_RD2063_01_s _ 2013_37 | | | | |
| Action/Comments | | | | | |
| No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |

No Photos

| | | | | | |
|---|---------------------------|--------------|----|------------------------|---------------|
| LM Start | 3.35 | Rating ** | M | Issue No. | 38 |
| LM End | 3.64 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 37.440438 ° | 37.436906 ° |
| | | | | -121.020487 ° | -121.017835 ° |
| DWR ID | DWR_RD2063_01_f _ 2012_38 | | | | |
| Action/Comments | | | | | |
| Remove the wild growth other than native grasses from the levee slopes. | | | | | |
| Inspector Comments: Control Johnson grass at landward toe. | | | | | |
| | | | | | |

Photo 1 of 1 : SP_2015_RD2063_112_38_20150514_00030.jpg



Looking south at vegetation at landward toe.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2063 Crows Landing

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|-------|------------|--------------------------|--------------------|
| Unit No. 01 San Joaquin River | Right | 10.44 | 05/12/2015 05/12/2015 | Richard Willoughby |

| | | | | | |
|--|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 3.49 | Rating ** | M | Issue No. | 53 |
| LM End | 3.49 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 37.438697 ° | 37.438697 ° |
| | | | | -121.019232 ° | -121.019232 ° |
| DWR ID | DWR_RD2063_01_f_2014_53 | | | | |
| Action/Comments | | | | | |
| Exterminate rodents and backfill and compact or grout burrows. | | | | | |

Photo 1 of 1 : SP_2015_RD2063_112_53_20150309_00012.jpg



Looking north at typical view of rodent holes on waterward slope.

| | | | | | |
|--|-------------------------|--------------|-----|------------------------|---------------|
| LM Start | 3.71 | Rating ** | A/W | Issue No. | 29 |
| LM End | 3.76 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 37.436197 ° | 37.435732 ° |
| | | | | -121.016937 ° | -121.016090 ° |
| DWR ID | DWR_RD2063_01_s_2012_29 | | | | |
| Action/Comments | | | | | |
| No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |

Photo 1 of 1 : SP_2015_RD2063_112_29_20150309_00008.jpg



Looking at typical view of a squirrel hole on landside shoulder.

| | | | | | |
|--|-------------------------|--------------|-----|------------------------|---------------|
| LM Start | 4.64 | Rating ** | A/W | Issue No. | 20 |
| LM End | 4.64 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Trim / Thin Trees | | | 37.429892 ° | 37.429892 ° |
| | | | | -121.004768 ° | -121.004768 ° |
| DWR ID | DWR_RD2063_01_s_2012_20 | | | | |
| Action/Comments | | | | | |
| Trim trees to at least five feet above ground level. | | | | | |

No Photos

| | | | | | |
|-----------------|----------------------|--------------------------|---|-----------------------------------|--|
| * Location | | ** Rating | | + Issue Type | |
| LS : Land Side | N/A : Not Applicable | A : Acceptable | N : Not Inspected/Rated | Ma : Maintenance Deficiency | |
| WS : Water Side | | M : Minimally Acceptable | C : Corrected | Ob : Design & System Obsolescence | |
| CR : Crown | | U : Unacceptable | A/W : Acceptable but Monitor & Maintain | En : Enforcement | |

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2063 Crows Landing

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|-------|------------|--------------------------|--------------------|
| Unit No. 01 San Joaquin River | Right | 10.44 | 05/12/2015 05/12/2015 | Richard Willoughby |

| | | | | | |
|--|--------------------------|--------------|-----|------------------------|---------------|
| LM Start | 5.99 | Rating ** | A/W | Issue No. | 5 |
| LM End | 5.99 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 37.415887 ° | 37.415887 ° |
| | | | | -120.998083 ° | -120.998083 ° |
| DWR ID | DWR_RD2063_01_s _ 2012_5 | | | | |
| Action/Comments | | | | | |
| Exterminate rodents and backfill and compact or grout burrows. | | | | | |

No Photos

| | | | | | |
|---|----------------------------|--------------|-----|------------------------|---------------|
| LM Start | 6.04 | Rating ** | A/W | Issue No. | 120 |
| LM End | 6.26 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 37.415488 ° | 37.413473 ° |
| | | | | -120.998988 ° | -121.001680 ° |
| DWR ID | DWR_RD2063_01_s _ 2012_120 | | | | |
| Action/Comments | | | | | |
| Remove the wild growth other than native grasses from the levee slopes. | | | | | |

Photo 1 of 1 : SP_2015_RD2063_112_120_20150309_00014.jpg



Looking south at dense vegetation on landside toe.

| | | | | | |
|--|---------------------------|--------------|----|------------------------|---------------|
| LM Start | 6.21 | Rating ** | M | Issue No. | 40 |
| LM End | 6.21 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Trim / Thin Trees | | | 37.414110 ° | 37.414110 ° |
| | | | | -121.001408 ° | -121.001408 ° |
| DWR ID | DWR_RD2063_01_s _ 2015_40 | | | | |
| Action/Comments | | | | | |
| Trim trees to at least five feet above ground level. | | | | | |

No Photos

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2063 Crows Landing

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|-------|------------|--------------------------|--------------------|
| Unit No. 01 San Joaquin River | Right | 10.44 | 05/12/2015 05/12/2015 | Richard Willoughby |

| | | | | | |
|--|---------------------------|--------------|-----|------------------------|---------------|
| LM Start | 6.67 | Rating ** | A/W | Issue No. | 41 |
| LM End | 6.70 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 37.411877 ° | 37.411725 ° |
| | | | | -120.995685 ° | -120.995092 ° |
| DWR ID | DWR_RD2063_01_s _ 2013_41 | | | | |
| Action/Comments | | | | | |
| No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |

No Photos

| | | | | | |
|--|---------------------------|--------------|-----|------------------------|---------------|
| LM Start | 6.89 | Rating ** | A/W | Issue No. | 39 |
| LM End | 6.89 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Trim / Thin Trees | | | 37.411785 ° | 37.411785 ° |
| | | | | -120.993548 ° | -120.993548 ° |
| DWR ID | DWR_RD2063_01_s _ 2012_39 | | | | |
| Action/Comments | | | | | |
| Trim trees to at least five feet above ground level. | | | | | |

No Photos

| | | | | | |
|---|--------------------------|--------------|----|------------------------|---------------|
| LM Start | 7.35 | Rating ** | M | Issue No. | 6 |
| LM End | 7.35 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Encroachments | | | 37.404377 ° | 37.404377 ° |
| | | | | -120.988852 ° | -120.988852 ° |
| DWR ID | DWR_RD2063_01_f _ 2014_6 | | | | |
| Action/Comments | | | | | |
| Tree or limb | | | | | |
| Inspector Comments: Fallen tree limbs at waterward toe. | | | | | |

Photo 1 of 1 : SP_2015_RD2063_112_6_20150309_00002.jpg



Looking southwest at fallen tree limbs at waterward toe.

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2063 Crows Landing

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|-------|------------|--------------------------|--------------------|
| Unit No. 01 San Joaquin River | Right | 10.44 | 05/12/2015 05/12/2015 | Richard Willoughby |

| | | | | | |
|---|------------------------|--------------|-----|------------------------|---------------|
| LM Start | 7.56 | Rating ** | A/W | Issue No. | 7 |
| LM End | 7.56 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Trim / Thin Trees | | | 37.403516 ° | 37.403516 ° |
| | | | | -120.985718 ° | -120.985718 ° |
| DWR ID | DWR_RD2063_01_s_2012_7 | | | | |
| Action/Comments | | | | | |
| Trim trees over roadway to at least 12 feet above ground level. | | | | | |

Photo 1 of 1 : SP_2015_RD2063_112_7_20150309_00003.jpg



Looking north at overhanging tree on landward slope.

| | | | | | |
|---|-------------------------|--------------|-----|------------------------|---------------|
| LM Start | 7.68 | Rating ** | A/W | Issue No. | 23 |
| LM End | 7.77 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 37.402400 ° | 37.401563 ° |
| | | | | -120.984087 ° | -120.982775 ° |
| DWR ID | DWR_RD2063_01_s_2012_23 | | | | |
| Action/Comments | | | | | |
| Remove the wild growth other than native grasses from the levee slopes. | | | | | |

No Photos

| | | | | | |
|---|------------------------|--------------|-----|------------------------|---------------|
| LM Start | 7.74 | Rating ** | A/W | Issue No. | 9 |
| LM End | 7.74 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Trim / Thin Trees | | | 37.401774 ° | 37.401774 ° |
| | | | | -120.983132 ° | -120.983132 ° |
| DWR ID | DWR_RD2063_01_s_2012_9 | | | | |
| Action/Comments | | | | | |
| Trim trees over roadway to at least 12 feet above ground level. | | | | | |

No Photos

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2063 Crows Landing

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|-------|------------|--------------------------|--------------------|
| Unit No. 01 San Joaquin River | Right | 10.44 | 05/12/2015 05/12/2015 | Richard Willoughby |

| | | | | | |
|---|---------------------------|--------------|----|------------------------|---------------|
| LM Start | 8.63 | Rating ** | M | Issue No. | 43 |
| LM End | 8.69 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 37.395752 ° | 37.394933 ° |
| | | | | -120.970823 ° | -120.970225 ° |
| DWR ID | DWR_RD2063_01_s _ 2015_43 | | | | |
| Action/Comments | | | | | |
| Remove the wild growth other than native grasses from the levee slopes. | | | | | |
| Inspector Comments: Control Johnson Grass at landward toe. | | | | | |
| | | | | | |

No Photos

| | | | | | |
|--|---------------------------|--------------|-----|------------------------|---------------|
| LM Start | 8.89 | Rating ** | A/W | Issue No. | 25 |
| LM End | 8.89 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 37.392405 ° | 37.392405 ° |
| | | | | -120.968492 ° | -120.968492 ° |
| DWR ID | DWR_RD2063_01_s _ 2013_25 | | | | |
| Action/Comments | | | | | |
| No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |

No Photos

| | | | | | |
|--|---------------------------|--------------|----|------------------------|---------------|
| LM Start | 10.38 | Rating ** | M | Issue No. | 42 |
| LM End | 10.43 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Erosion / Bank Caving | | | 37.390503 ° | 37.390483 ° |
| | | | | -120.942368 ° | -120.941480 ° |
| DWR ID | DWR_RD2063_01_s _ 2013_42 | | | | |
| Action/Comments | | | | | |
| Schedule repair of erosion site prior to the next inspection. Inspector Comments: Repair erosion on waterward shoulder. Erosion cause by farm equipment. | | | | | |

Photo 1 of 1 : SP_2015_RD2063_112_42_20150309_00011.jpg



Looking north at erosion on waterward shoulder.

| | | | | | |
|-----------------|----------------------|--------------------------|---|-----------------------------------|--|
| * Location | | ** Rating | | + Issue Type | |
| LS : Land Side | N/A : Not Applicable | A : Acceptable | N : Not Inspected/Rated | Ma : Maintenance Deficiency | |
| WS : Water Side | | M : Minimally Acceptable | C : Corrected | Ob : Design & System Obsolescence | |
| CR : Crown | | U : Unacceptable | A/W : Acceptable but Monitor & Maintain | En : Enforcement | |